



Fig. 1

CONVENTIONAL ART




Fig. 2

CONVENTIONAL ART

Flow	Electron Beam Patterning Process	Laser Beam Patterning Process
Receipt of Blank		
Exposure/Patterning	Electron Beam Patterning Device	Laser Beam Patterning Device
Development	Spray, Dip, Paddle Systems Organic Solvent Development Alkali Development	Alkali Development
Post-Baking	Hot Plate Oven Convection Oven	Generally, any treatment is not required.
De-scumming	Plasma De-scumming Device	Generally, any treatment is not required.
CrEtching	Wet Etching and Dry-Etching	
Removal of Resist	Solvent Peeling, Ashing	Exposure of Whole Surface/Alkali Peeling, Solvent Peeling, Ashing
Washing	Sheet-Fed Acid-Treatment, Physical Scrubbing, or the like	
To Inspection Step		